



**Allsworth  
Roofing**



Cotswold Stone Slating, Tiling & Leadwork

TELEPHONE **01993 846444** and Mobile **07889 348130**

**www.allsworthroofing.com**

TS64 ANU

G674 ECV











St Mary the Virgin Church, Barton, Oxon - Condition Survey

vii) Investigate timber sub-floor at east end of Nave for subsidence/decay; carry out remedial work if necessary.

viii) Carry out minor repairs to churchyard boundary gates.

ix) Commission test inspection/report on electrical installation following NICEIC recommended format. Act on urgent recommendations.

8.04 Works which may be required beyond five years or are desirable within five years

i) Ongoing minor pointing and repairs to masonry are likely to be required.

ii) Renew lead sheet coverings to south porch roof incorporating improved detailing including repairs to supporting roof structure as required (subject to findings during the patch repairs in 8.01 iii) above, this work may be considered to be more urgent). Further minor repairs to remaining lead covered roofs may also be required at this time.

iii) General review of stored items in clock chamber, chancel porch and Hordle

APPENDIX A  
Photographs

Page 22 of 22  
Appendix A  
Photographs

Appendix A  
Photographs



















