



After full restoration in 1870s this view inside St Mary The Virgin is taken looking from the west door to the altar. Before the restoration, the reredos seen here on the east wall behind the altar was in the Lady Chapel, the floor up to the altar was all one level and a heating system with the grids over the hot pipes did not exist immediately. Note the This picture is very similar to several taken in the church and around Bampton by Henry Taunt.